

Project No.	Client	Location	Boring No.	Monitoring Well No.	Date
01105	Metro Car Wash	2950 Harbor, CM	CB-5	N/A	August 10, 2005
PID	BLOWS/ft. Sampler	DEPTH in feet	USCS Designation & Soil Type	Color	Secondary Characteristics
0	7-9-11	5	CL-Sandy Clay	Dark Brown	Stiff, Sl Damp, No Odor
0	8-12-15	10			Dry
0	8-13-16	15	CL-Silty Clay	Brown	Trace Silt
0	9-10-14	20			
0	10-12-16	25		Tan to Brown	
0	12-14-16	30		Dark Brown	
0	8-12-16	35	CL-Sandy Clay		
15	9-11-15	40		Light Brown	Trace Odor
0	10-12-14	45	SM-Silty Sand	Tan	Dense, Damp, No Odor
0	12-15-17	50			
0	9-12-17	55		Light Grey	Moist
40	9-14-16	60			Slight Odor
20	10-12-14	65		Tan to Grey	Slight Odor
50	7-13-17	70		Light Grey to Grey	Wet, Slight Odor
20	8-14-18	75	SP-Poorly Graded Sands		Slight Odor
Field Engineer	Drilling Contractor	Drilling Foreman	Boring terminated at 75 feet below grade. Groundwater at 67'. Boring backfilled with soil of origin and capped with bentonite plug (2'). Resurfaced with concrete		
M. Anselmo	J & H	Conrad			